

KEY	PART NO.	DESCRIPTION
01	130413-000	Screw
02	134946-000	Housing Left
03	134940-000	Housing Right
04	134939-000	Safety
05	133106-000	Pump Handle
06	134927-000	Piercing Screw
07	133405-000	Trigger
08	133440-000	Hopper Release Button
09	133494-000	Hammer Compression Spring
10	137577-000	Trigger Spring
11	164908-000	Hammer Assembly
12	164910-000	Bolt Assembly
13	165204-000	Valve Body Assembly
14	165322-000	Hopper Assembly

Marker Fails to Discharge	Marker is not Cocked	Cock Marker Pump Handle
Marker Fails to Discharge	Lack of Gas Pressure	Install New 12gram CO2 Cylinders
Marker Fails to Discharge	Gas Source Not Fully Engaged	Tighten Piercing Screw - Do Not Over Tighten!
Marker Fails to Discharge	Operating Temperature Too Cold	Operate in Warmer Temperature
Marker Fails to Discharge	Broken Paintball	Squeegee Out Paintball Fragments in Barrel

